


Soartronic IOIO UART interface v2e assembly manual




www.soartronic.com

This manual is for both
IOIO v1 and **IOIO-OTG**

Components assembled should look like this:

components marked with **RED** arrows have polarity, and must be soldered as shown in the picture.

Also make sure that the holes of micro-ships marked with **YELLOW** arrows are as shown on the picture.



The **BLUE** arrows show places for extra components, which may be used to filter the 5V output from IOIO-OTG card. We have not tested this, and it is likely that placing coil and capacitor do not really help – but if you test (and I suppose you know what you are doing..) please tell us what was the result...


IF you have the first generation IOIO card which looks like this:




You should connect the points marked with white circles on back side of the Soartronic IOIO UART interface board. One circle is marked with RED arrow for an example.

We also recommend to connect the corners for IOIO card stability (corners marked with YELLOW arrow)

You MUST also connect jumper wire between these two connection holes marked with WHITE arrow.




IF you have the second generation card, IOIO-OTG card which looks like this:




You should connect the points marked with white circles on top side of the Soartronic IOIO UART interface board. One circle is marked with RED arrow for an example.

We also recommend to connect the corners for IOIO card stability (one corners marked with YELLOW arrow)


You MUST also connect jumper wires (both marked with short RED lines) between these connection holes marked with WHITE arrow.



In earlier shown example pictures surface mounted capacitors were used. If you have through hole components, your board will look more like this:




And this:



Note also on the above picture the orientation of the larger capacitors, they have polarity. The small ones do not. The coil in this picture may have been replaced with ferrite, as shown in the earlier pictures.

ON the backside of the Soartronic UART Interface V2e there are 3 connection points to connect 12V or 5 V lines to the RJ45 connectors. These jumpers are marked with YELLOW arrows in this picture:



JP1 connects 12V to the Flarm and Display RJ45 connectors according to IGC standard. If JP1 is not connected, 12V line is NOT connected.

JP2 connects 12V to the UART RJ45 connectors according to IGC standard. If JP1 is not connected, 12V line is NOT connected.

JP3 connects UART_1 RJ45 connector pin6 with the 5V line of the Soartronic IOIO UART Interface and the IOIO card. This can be used to power the IOIO card, or to feed 5V out of the card. If powered from outside with 5V THE 12V LINE MUST NOT BE CONNECTED!

About the use of JP1:

If you have FLARM that has already 12V supply, and you want to keep that instead of feeding 12V from Soartronic IOIO interface, do not connect JP1. If your FLARM has separate 12V/GND wires connected, you just connect the Flarm port to the FLARM dataport with straight RJ cable. RS232 data communication is now connected.

If you have a RJ cable feeding power to your FLARM, disconnect that RJ cable from FLARM and connect it to the UART 0 / Flarm RJ45 port, and then add a new straight RJ cable between Soartronic IOIO interface Flarm connector and FLARM. Now RS232 data communication is connected, and 12V from outside source is relayed through the RJ45 splitter to your FLARM device.

If you solder connection over JP1 the UART 0 Flarm and Display RJ45 connectors will feed 12V to your cable according to IGC standard. With one cable you can feed power to your FLARM and read/write RS232 data.


About the use of JP2

JP2 connects 12V to the UART 1 RJ45 connector.

JP2 is use to connect 12V to the RJ45 connector according to IGC standard. This way you can connect RS232 communication and 12V power to devices like Volkslogger, and some Colibri loggers.

Before connecting any logger or other device, please make sure that your device uses IGC standard RJ connector, and that your RJ cable is straight.

Straight (Trough) RJ cable vs. other possible connections:



About the use of JP3


Do not solder JP3 if you do not know what you are doing.

JP3 connects 5V of the IOIO card to the pin 6 of the UART 1 RJ45 connector.

If 12V is supplied to the IOIO card, this 5V is generated by the IOIO card, and then fed out via pin 6.

If 5 V is generated by the device that is connected to this pin 6, it can be used by the IOIO card instead of its own 5V regulated from the 12V supply voltage. In that case 12V should NOT be connected to the Soartronic IOIO UART interface!



Diode direction print is missing from many UART interface boards, since it was placed too close to copper. The white arrows in his picture shows how to solder the diodes:




(the holes next to the two diodes is for fixing wires connected to UART2 and UART3 using narrow wire straps.)

Place pin-headers for **the first generation IOIO card** as shown in images below.

THIS IS IMPORTANT!!! For first generation IOIO make sure the voltage and GND connection pins are exactly as shown here, and as marked with white circles





One pin that is used to connect voltage measurement to 12V line is missing from these pictures! Place for that pin is marked with RED arrow, and it is marked with white circle.





You should have IOIO kard like this...

Place pin-headers for **IOIO-OTG card** as shown in images below.

THIS IS IMPORTANT!!! For IOIO OTG make sure the voltage and GND connection pins are exactly as shown here, and as marked with white circles



The pin that is used to connect voltage measurement to 12V line is missing from these pictures! Place for that pin is marked with RED arrow, and it is marked with white circle on the circuit-board.




You should have IOIO-OTG card like this...

Finally solder the IOIO card.

The USB connector should point into the opposite direction with the RJ45 connectors, and all the components and the USB connector should be on the TOP.

Just for an example:




This picture shows jumpers for

- **Connecting 12V line to FLARM RJ45 cables**
- **Connecting jumpers for use with IOIO-OTG**

>> In this example FLARM is powered from Soartronic interface card, and IOIO-OTG is used. >>

IOIO UART interface connections:



- A) UART 0, FLARM splitter. These two RJ45 IGC standard ports are connected together as a “RJ45 splitter”. Port market “FLARM” can communicate with FLARM. “DISPLAY” port can be used to forward FLARM communication to other devices like display units, variometers, etc. *Please note that this splitter is intelligent. This means, that you can have two devices communication with FLARM without need of a “declare/fly” switch, as long as they do not write to FLARM simultaneously!*
- B) UART 1, another IGC standard RJ45 connector. This can connect with loggers and variometers with IGC standard RJ45 or RJ12 ports.
- C) UART 2, Connection points for RS232 level serial communication (RX/TX/GND). Solder here connection wires to SUBD9 connectors or other special connectors. Use the holes in PCB for fixing the wires using narrow wire straps.
- D) UART 3, Connection points for TTL level serial communication (RX/TX/GND). You can connect here TTL level serial communication devices like Bluetooth chips, come loggers, etc. You can also use an external TTL/RS232 converter if you need to use all 4 UARTs.