


Extra features of IOIO uart interface v2a

Battery monitor parts:

R2 24k resistor (red yellow orange)

R3 6.8k resistor (blue gray red)

D4 not used



**BLACK
RING**

Please note!


Battery monitor components have been selected to measure the 12-volt battery.

If a higher voltage is used, battery monitor units should not be installed.

Led indicator

R1 470 resistor (yellow violet brown)

D3 led



Add two pins to make connection between uart interface and ioio.

